

# Final Reclamation and Stormwater Inspection

May 28, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 320397

Inspection Document #: 674902147

Adams County, CO

NENE Section 1 T1S R66W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

**Inspection Photos**  
**Location Name: KERR MCGEE /1S66W1**  
**Location ID: 320397**



**Photo 1.** Photo taken from the location, facing Southeast. Appears the Operator has performed final reclamation activities on the well location, with the evidence of drilling rows, straw crimped mulch. However, the majority of the site is covered in weedy, annual vegetation which includes but not limited to field bindweed, Russian thistle, cheatgrass and kochia, with little perennial grass cover establishment. A List B Colorado Noxious weed species, Scotch thistle (*Onopordum acanthium*), is found at low densities throughout the site .



**Photo 2.** Photo taken from the location, facing Southwest. See comments under Photo 1.



Inspection Photos  
Location Name: KERR MCGEE /1S66W1  
Location ID: 320397



**Photo 3.** Photo taken from the location, facing Southeast showing a barren patch of the disturbance area where reclamation has not been completed and is full of noxious and annual weeds that is adjacent to the location. See comments under Photo 1.



**Photo 4.** Photo taken along access road, facing Northeast. The majority of the access road remains with no reclamation activities.

Inspection Photos  
Location Name: KERR MCGEE /1S66W1  
Location ID: 320397



**Photo 5.** Photo taken from the facility location, facing Southeast. Appears the Operator has performed final reclamation activities on the facility location, with the evidence of drilling rows, straw crimped mulch. See comments under Photo 1.



**Photo 6.** Photo taken from the facility location, facing Northeast showing the access road through the facility location has not been reclaimed.