

Inspection Photos
Location Name: Ray Ranch 0780 16
Location ID: 446527



Photo 1. Overview of location taken from northeast side facing southwest.



Photo 2. Overview of location taken from entrance facing southeast.

Inspection Photos
Location Name: Ray Ranch 0780 16
Location ID: 446527



Photo 3. No wellhead signs.



Photo 4. Battery sign at entrance with incorrect information.

Inspection Photos
Location Name: Ray Ranch 0780 16
Location ID: 446527



Photo 5. Trash on location from build.



Photo 6. Trash on location from build.

Inspection Photos
Location Name: Ray Ranch 0780 16
Location ID: 446527



Photo 7. No capacity on tank labels.



Photo 8. Tank labels only visible from inside berm.

Inspection Photos
Location Name: Ray Ranch 0780 16
Location ID: 446527



Photo 9. Equipment stored on location.



Photo 10. Equipment stored on location.