



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing, largely with grasses such as western wheatgrass (*Pascopyrum smithii*) and crested wheatgrass (*Agropyron cristatum*).



Photo 3. View of the southern portion of the project area from the southwestern project area facing eastward.





Photo 4. View of metal debris in the southeastern project area.



Photo 5. View of wood debris within the eastern portion of the project area.