

Inspection Photos
Location Name: McCallum Unit 96
API: 05-057-06160



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. No current operator or emergency number on location.