

Inspection Photos
Location Name: McCallum Unit 109
API: 05-057-06264



**Photo 1. Overview of location taken at entrance facing northwest.
No current operator or emergency number on sign.**