

Inspection Photos

06/01/2018

Operator: MAGPIE OPERATING, INC - 52530

Location ID: 401718

Inspection Doc. Number: 682503397

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 401718



Photo 1: Photo taken from the northeast end of the pit location, facing south. Photo shows areas of the pit remain predominantly bare and exposed soil. Vegetation seen in photo largely undesirable weedy plant species such as cheat grass. Unable to find evidence that additional reclamation activities have been conducted in accordance to reclamation requirements and standards, or per corrective actions.



Photo 2: Photo taken from the east end of the pit location, facing south. See comments under photo 1.

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 401718



Photo 3: Photo taken from the pit location. Photo shows areas of the pit that remains bare and exposed soil. Photo also show that no evidence of additional reclamation activities could be found.



Photo 4: Photo taken from the southeast end of the pit location, facing west. See comments under photo 1.

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 401718



Photo 5: Photo taken from the southwest end of the pit location, facing north. See comments under photo 1.



Photo 6: Photo taken from the west end of the pit location, facing north. See comments under photo 1.



Photo 6: Photo taken from the west end of the pit location. Photo shows what appears to be a barrel remains on the location. This debris was identified in previous inspections and was required to be removed. Photo shows debris has not been removed.