

Inspection Photos  
Well Name: PVGP SCU 0992-18-09W  
Location ID: 311747



**Photo 1. Location view of H&P Rig 290.**



**Photo 2. Parking area along access road near entrance.**

Inspection Photos  
Well Name: PVGP SCU 0992-18-09W  
Location ID: 311747



**Photo 3. Irrigation water leaving ditch along cut slope.**



**Photo 4. Water leaving disturbance area and going into pasture.**