

Final Reclamation Inspection

June 4, 2018

Operator: SUNDANCE ENERGY INC - 10340

Location ID: 432932

Inspection Document #: 674902164

Weld County, CO

NENE Section 19 T2N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SUNDANCE ENERGY/2N66W19
Location ID: 432932



Photo 1. Photo taken from State Highway 85 facing West into proposed location. Well Location was not constructed at the proposed location based on field observations.