

Inspection Photos

API#081-06928

Operator: Western Gas Resources

Inspection Number: 674104447

Inspection Date: 5/25/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to East. Arrow indicates what appears to be Well head noted on site

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Western Gas Resources PA Martin API#081-06928



Photo#2: Close up views of what appears to be Well head noted on site.



Photo#3:

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Western Gas Resources PA Martin API#081-06928



Photo#4:

There are bare compacted areas. Site appears to be utilized as livestock loafing area.

Photo#5:

May 25, 2018



Photo#6:
Debris is present on perimeter of Location.

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Western Gas Resources PA Martin API#081-06928



Photo#7:
Close up of ground conditions at compacted areas of site.

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Western Gas Resources PA Martin API#081-06928