

Photo log for Response to May 24, 2018 Inspection

COGCC conducted an inspection of the Hagermiester 43-6 location (Location ID 306472) on May 24, 2018 (Document 684905453). During that inspection, COGCC made the following observation:

Storm Water: Stormwater erosion at SW side of location.

Response: Noble repaired the erosion.

COGCC – 5/24/18



Photo 4: Stormwater erosion at SW corner of location.

Noble Energy – 5/30/18



Photo NBL1. Noble repaired the erosion.