

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	May 31, 2018 4:06:39 PM MDT
Server Receive Date:	May 31, 2018 4:06:46 PM MDT
Reference Number:	20180531-1879877087
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA May 31, 2018 4:06:38 PM MDT [View Map]

Information

Name	reclamationtablet
Date	May 31, 2018
Well Name	STATE CF 1 GAS COM
API Number	50670792700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Grading/recontour Erosion Repairs Install Wattles Clean up Operator Debris Clean Up Land Owner Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

Work completed per scope of work