

Inspection Photos

Loc#428533

Operator: GRMR

Inspection Number: 674104454

Inspection Date: 5/25/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources




Photo#1:
View over Location center to West.

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR North Castor Gulch Loc#428533



Photo#2:

View out of Location to Northeast over problematic area where reclaimed area of location meets existing Access road turnaround (where Jeep is Parked).

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR North Castor Gulch Loc#428533



Photo#3:
A few areas, bare of vegetation or weed infested are eroding.



Photo#4:

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR North Castor Gulch Loc#428533



Photo#5:
Noxious Weed, Bull Thistle on Site .



Photo#6:
Noxious Weed, Whitetop on Site.

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Inspection Photos: GRMR North Castor Gulch Loc#428533



Photo#7:

Blue Mustard & Pennycress, that become debris & are so populous as to be competing with desirable vegetation.

May 25, 2018



Photo#8: