

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2018

Submitted Date:

06/06/2018

Document Number:

689701424**FIELD INSPECTION FORM**

Loc ID 335607	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 18 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:			
OGCC Operator Number: <u>10456</u>			
Name of Operator: <u>CAERUS PICEANCE LLC</u>			
Address: <u>1001 17TH STREET #1600</u>			
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>	

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282086	WELL	PR	10/14/2009	GW	045-11643	N. PARACHUTE EF06D L29 595	PR
282087	WELL	PR	08/16/2007	GW	045-11642	N. PARACHUTE EF06B L29 595	PR
282089	WELL	PR	04/26/2008	GW	045-11641	N. PARACHUTE EF03D-32 L29 59	PR
282090	WELL	PR	08/21/2007	GW	045-11640	N.PARACHUTE EF03D L29 595	PR
282091	WELL	PR	11/01/2012	GW	045-11644	N. PARACHUTE EF04D-32 L29 59	PR
282092	WELL	PR	11/01/2012	GW	045-11639	N. PARACHUTE EF12B L29 595	PR
282095	WELL	PR	11/01/2012	GW	045-11638	N.PARACHUTE EF13B L29 595	PR
282096	WELL	PR	02/01/2014	GW	045-11637	N.PARACHUTE EF05B-32 L29 59	PR
282097	WELL	PR	08/21/2007	GW	045-11636	N.PARACHUTE EF06B-32 L29 59	PR
282098	WELL	PR	01/25/2007	GW	045-11635	N.PARACHUTE EF06C-32- L29 59	PR
282102	WELL	PR	04/03/2007	GW	045-11650	N.PARACHUTE EF04B L29 595	PR
282103	WELL	PR	04/03/2007	GW	045-11649	N.PARACHUTE EF05B L29 595	PR
282104	WELL	PR	04/03/2007	GW	045-11648	N.PARACHUTE EFO6D-32 L29 59	PR
282105	WELL	PR	04/03/2007	GW	045-11647	N.PARACHUTE EF13D L29 595	PR
282106	WELL	PR	02/14/2007	GW	045-11646	N.PARACHUTE EF03C L29 595	PR
282107	WELL	PR	08/16/2007	GW	045-11645	N. PARACHUTE EFO6A-32 L20 59	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containers		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282086	Type:	WELL	API Number:	045-11643	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282087	Type:	WELL	API Number:	045-11642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282089	Type:	WELL	API Number:	045-11641	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282090	Type:	WELL	API Number:	045-11640	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282091	Type:	WELL	API Number:	045-11644	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282092	Type:	WELL	API Number:	045-11639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282095	Type:	WELL	API Number:	045-11638	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282096	Type:	WELL	API Number:	045-11637	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	282097	Type:	WELL	API Number:	045-11636	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282098	Type:	WELL	API Number:	045-11635	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282102	Type:	WELL	API Number:	045-11650	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282103	Type:	WELL	API Number:	045-11649	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282104	Type:	WELL	API Number:	045-11648	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282105	Type:	WELL	API Number:	045-11647	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282106	Type:	WELL	API Number:	045-11646	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282107	Type:	WELL	API Number:	045-11645	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Compaction	Pass			
Seeding	Pass					
		Gravel	Pass			
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
Berms	Pass					
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701425	Inspection 689701424 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4487239