

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2018

Submitted Date:

06/06/2018

Document Number:

689701426**FIELD INSPECTION FORM**

Loc ID 335588	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 26 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:			
OGCC Operator Number: <u>10456</u>			
Name of Operator: <u>CAERUS PICEANCE LLC</u>			
Address: <u>1001 17TH STREET #1600</u>			
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>	

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280381	WELL	PR	02/01/2014	GW	045-11246	N.PARACHUTE EF01B 130 595	PR
280387	WELL	PR	04/12/2007	GW	045-11251	N.PARACHUTE EF08B 130 595	PR
280388	WELL	PR	09/17/2008	GW	045-11250	N.PARACHUTE EF 08D 130 595	PR
280389	WELL	PR	07/20/2006	GW	045-11249	N.PARACHUTE EF 16D 130 595	PR
280390	WELL	PR	04/19/2007	GW	045-11248	N.PARACHUTE EF16B I30 595	PR
280391	WELL	PR	06/22/2006	GW	045-11247	N.PARACHUTE EF04B 130 595	PR
280439	WELL	PR	02/01/2014	GW	045-11252	N.PARACHUTE EF01D-31 I30 59	PR
280440	WELL	PR	07/21/2006	GW	045-11253	N. PARACHUTE EF01D I30 595	PR
294239	WELL	PR	07/26/2009	GW	045-15341	N. PARACHUTE EF16C-19 I30 59	PR
294240	WELL	PR	02/19/2009	GW	045-15342	N. PARACHUTE EF03A-29 I30 59	PR
294241	WELL	PR	02/24/2009	GW	045-15343	N. PARACHUTE EF05C-29 I30 59	PR
294242	WELL	PR	02/11/2009	GW	045-15344	N.PARACHUTE EF12D-29 I30 59	PR
294261	WELL	PR	02/20/2009	GW	045-15345	N.PARACHUTE EF13A-29 I30 59	PR
294262	WELL	PR	08/11/2009	GW	045-15346	N. PARACHUTE EFO1B-30 I30 59	PR
294263	WELL	PR	02/20/2009	GW	045-15347	N.PARACHUTE EF13C-29 I30 59	PR
294264	WELL	PR	07/20/2009	GW	045-15348	N. PARACHUTE EF04D-29 I30 59	PR

294265	WELL	PR	07/25/2009	GW	045-15349	N. PARACHUTE EF04C-29 I30 59	PR
294266	WELL	PR	02/11/2009	GW	045-15350	N. PARACHUTE EF05A-29 I30 59	PR
294267	WELL	PR	07/27/2009	GW	045-15351	N.PARACHUTE EF08A-30 I30 59	PR
294268	WELL	PR	08/17/2009	GW	045-15352	N.PARACHUTE EF08C-30 I30 59	PR
294269	WELL	PR	03/22/2009	GW	045-15353	N.PARACHUTE EF04A-32 I30 59	PR
294270	WELL	PR	02/19/2009	GW	045-15354	N.PARACHUTE EF05D-29 I30 59	PR
294271	WELL	PR	09/15/2009	GW	045-15355	N. PARACHUTE EF04A-29 I30 59	PR
294272	WELL	PR	07/28/2009	GW	045-15356	N. PARACHUTE EF16D-19 I30 59	PR

General Comment:

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Chemical containers		
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	280381	Type:	WELL	API Number:	045-11246	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280387	Type:	WELL	API Number:	045-11251	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280388	Type:	WELL	API Number:	045-11250	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280389	Type:	WELL	API Number:	045-11249	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280390	Type:	WELL	API Number:	045-11248	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280391	Type:	WELL	API Number:	045-11247	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280439	Type:	WELL	API Number:	045-11252	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280440	Type:	WELL	API Number:	045-11253	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	294239	Type:	WELL	API Number:	045-15341	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294240	Type:	WELL	API Number:	045-15342	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294241	Type:	WELL	API Number:	045-15343	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294242	Type:	WELL	API Number:	045-15344	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294261	Type:	WELL	API Number:	045-15345	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294262	Type:	WELL	API Number:	045-15346	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294263	Type:	WELL	API Number:	045-15347	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294264	Type:	WELL	API Number:	045-15348	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	294265	Type:	WELL	API Number:	045-15349	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294266	Type:	WELL	API Number:	045-15350	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294267	Type:	WELL	API Number:	045-15351	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294268	Type:	WELL	API Number:	045-15352	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294269	Type:	WELL	API Number:	045-15353	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294270	Type:	WELL	API Number:	045-15354	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294271	Type:	WELL	API Number:	045-15355	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	294272	Type:	WELL	API Number:	045-15356	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Culverts	Pass			
Check Dams	Pass					
				Material Handling And Spill Prevention	Pass	
Compaction	Pass					
		Ditches	Pass			
Ditches	Pass					
Berms	Pass					
Gravel	Pass					
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701427	Inspection 689701426 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4487240