

Inspection Photos
Well Name: South Shale Ridge 1-14H
Location ID: 324270



Photo 1. Vegetation still present in tank containment and on berm.



Photo 2. Cut off wellhead stored near tank containment.