

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



Netting on open tanks inadequate. Wildlife protection devices not adequate



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



Some of the compressor equipment has been removed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



Some of the compressor equipment has been removed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Wind Mill Compressor

Facility #: 438220

Inspection Date: 6/4/2018



Inadequate berms around tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources