

# Final Reclamation and Stormwater Inspection

May 28, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 320405

Inspection Document #: 674902144

Adams County, CO

SWNW Section 5 T1S R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /1S65W5  
Location ID: 320405



**Photo 1.** Photo taken from the location entrance, facing North. Appears the Operator has not performed final reclamation activities for the access road, the cattle guard and access road remain on location. A List B Colorado Noxious weed species, Scotch thistle (*Onopordum acanthium*), is found at high densities along the access road and on location.



**Photo 2.** Photo taken from the location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: KERR MCGEE /1S65W5  
Location ID: 320405



**Photo 3.** Photo taken from location, facing Southeast. Equipment is still on location. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. However, the majority of the site is either barren or covered in weedy, annual vegetation which includes but not limited to cheatgrass and kochia.



**Photo 4.** Photo taken from location, facing East. See comments under Photo 3.

Inspection Photos

Location Name: KERR MCGEE /1S65W5

Location ID: 320405



**Photo 5.** Photo taken from the facility area, facing West along the access road. See comments under Photo 1.



**Photo 6.** Photo taken North of the access road, facing North showing the high density of scotch thistle on the adjacent property. See comments under Photo 1.