

Final Reclamation and Stormwater Inspection

June 4, 2018

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 318044

Inspection Document #: 674902172

Weld County, CO

NENW Section 32 T2N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/2N67W32

Location ID: 318044



Photo 1. Photo taken from the location, facing West. Appears the Operator has performed reclamation activities on the access road with all equipment removed. Gravel remains on the location which has not been re-contoured or re-graded and decompacted to meet the adjacent terrain



Photo 2. Photo taken from the location, facing North. See comments from Photo 1.

Inspection Photos
Location Name: EXTRACTION OIL & GAS INC/2N67W32
Location ID: 318044



Photo 3. Photo taken from the access road location, facing East. See comments from Photo 1.



Photo 4. Photo taken from the access road location, facing South. See comments from Photo 1.