

# Final Reclamation and Stormwater Inspection

June 7, 2018

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 323243

Inspection Document #: 674902187

Weld County, CO

SESE Section 23 T2N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W23

Location ID: 323243



**Photo 1.** Photo taken from the well location, facing East. Appears the Operator has performed reclamation activities. Equipment and debris remain.



**Photo 2.** Photo taken from location, facing West. See comments from Photo 1.



## Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W23

Location ID: 323243



**Photo 3.** Photo taken from location, facing Southwest. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. However, the portions of the site are covered in weedy, annual vegetation which includes but not limited to cheatgrass, field bindweed and kochia, with little perennial grass cover establishment. A List B Colorado Noxious weed species, musk thistle (*Carduus nutans*), is found at low densities throughout the site .



**Photo 4.** Photo taken within facility area. Note the musk thistle. See comments from Photo 3.