

**Inspection Photo**  
**Shideler 31-15 (031E)**  
**API # 045-11451**  
**Inspection # 689301272**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo**  
**HMU 6-11**  
**API # 045-11294**  
**Inspection # 689301270**



**Location Photo #3, cellars covered on location**



**Location Photo #4, Stained rock in tank battery containment**

**Inspection Photo**  
**HMU 6-11**  
**API # 045-11294**  
**Inspection # 689301270**



**Location Photo #5, Stained rock in tank  
battery containment**