

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401611176  
Date Received:  
04/17/2018

FIR RESOLUTION FORM

CA Summary:  
1 of 1 CAs from the FIR responded to on this Form  
1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Inspections, All		SanJuanCOGCC@bp.com
Beebe, Sabre	970-779-9398	Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685304478  
Inspection Date: 03/14/2018 FIR Submit Date: 03/16/2018 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325817

Location Name: JOHN BARNES GAS UNIT A Number: 4SWSE County: LA PLATA  
PLA-6-N33N9W  
Qtrqtr: SWSE Sec: 4 Twp: 33N Range: 9W Meridian: N  
Latitude: 37.129172 Longitude: -107.826562

FACILITY - API Number: 05-067-00 Facility ID: 215422

Facility Name: JOHN BARNES A Number: 1  
Qtrqtr: SWSE Sec: 4 Twp: 33N Range: 9W Meridian: N  
Latitude: 37.129172 Longitude: -107.826562

CORRECTIVE ACTIIONS:

1  CA# 114937

Corrective Action: Remove debris to comply with Rule 603.f. Date: 04/16/2018

Response: CA COMPLETED Date of Completion: 04/02/2018

Operator Comment: Debris and trash removed from location to address this corrective action see attached photos.

COGCC Decision: Approved

COGCC Representative: Approved based on operator submitted photo documentation.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA completed see attached photos. New sign is on order and will be installed upon arrival. Weed debris was removed and disposed of properly. Stained soils noted during work execution around the well head was cleaned up and disposed of in the BP soil box for batch remediation at IEI. See all photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: \_\_\_\_\_

Title: Compliance Specialist Date: 4/17/2018 1:49:51 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
401611176	FIR RESOLUTION SUBMITTED
401611187	CA and other work completed documentation

Total Attach: 2 Files