

Final Reclamation and Stormwater Inspection

June 7, 2018

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 323253

Inspection Document #: 674902194

Weld County, CO

SENE Section 23 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W23

Location ID: 323253



Photo 1. Photo taken from the access road looking towards the location, facing West. The gravel has not been removed and compaction has not been alleviated along the first part of the access road.



Photo 2. Photo taken from the access road, facing East. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W23

Location ID: 323253



Photo 3. Photo taken from the access road looking towards the location, facing West. See comments from Photo 1.



Photo 4. Close up photo taken from the access road showing the effects of compaction on the planted crops. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W23

Location ID: 323253



Photo 5. Photo taken from the well location, facing North.



Photo 6. Photo taken from the well location, facing West.