

# Final Reclamation Inspection

June 11, 2018

Operator: HOMESTEAD OIL INC - #41050

API: 05-123-16272

Inspection Document #: 682403674

Weld County, CO

SENW Section 15 T4N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BOULTER #15-24  
API: 05-123-16272



Google Earth aerial imagery taken February 29, 2008 of the well location and access road during active operations. Appears there was a disturbance between June 30, 2006 and August 30, 2006, located just west of the location.

Inspection Photos  
Location Name: BOULTER #15-24  
API: 05-123-16272



Google Earth aerial imagery taken October 14, 2017 post plugging operations. On June 11, 2018, Staff mapped the approximate area of stunted growth (line red). Other disturbance areas appeared to meet Rule 1004 standards.



Inspection Photos  
Location Name: BOULTER #15-24  
API: 05-123-16272



**Photo 1.** Photo taken from just west of the well location, facing North. Photo illustrates an area of stunted corn growth which is not reflective of reference area crop levels.



Inspection Photos  
Location Name: BOULTER #15-24  
API: 05-123-16272



**Photo 2.** Photo taken from the central area of stunted corn growth, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: BOULTER #15-24  
API: 05-123-16272



**Photo 3.** Photo taken of the approximate height of stunted corn which was approximately ankle height.





**Photo 4.** Photo taken of the approximate height of reference corn which was approximately knee height.



Inspection Photos  
Location Name: BOULTER #15-24  
API: 05-123-16272



**Photo 5.** Photo taken along a portion of the access road, facing South. Access road appears reflective of reference area crop levels.