

# Final Reclamation Inspection

June 11, 2018

Operator: EDDY OIL COMPANY - #26420

API: 05-123-14110

Inspection Document #: 682403678

Weld County, CO

NENW Section 24 T5N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: OGILVIE #24-3  
API: 05-123-14110



**Photo 1.** Photo taken from the start of the access road, facing East. Access road is evident and does not meet Rule 1004 standards. Access road appears to be compacted with undesirable vegetation, including noxious weeds (Canada and Musk Thistle).

Inspection Photos  
Location Name: OGILVIE #24-3  
API: 05-123-14110



**Photo 2.** Photo taken along the approximate midway point of the access road, facing East. See comments under Photo 1. Some desirable vegetation was observed along the middle portion of the access road.

Inspection Photos  
Location Name: OGILVIE #24-3  
API: 05-123-14110



**Photo 3.** Photo taken along the eastern access road, facing East. See comments under Photo 2.

Inspection Photos  
Location Name: OGILVIE #24-3  
API: 05-123-14110



**Photo 4.** Photo taken from the approximate well location, facing West. Desirable vegetation was observed throughout the well location and would appear to meet Rule 1004 standards.

Inspection Photos  
Location Name: OGILVIE #24-3  
API: 05-123-14110



**Photo 5.** Photo taken from the approximate well location, facing South. See comments under Photo 4.