

Final Reclamation and Stormwater Inspection

June 7, 2018

Operator: PDC ENERGY INC – 69175

Location ID: 336426

Inspection Document #: 674902192

Weld County, CO

NWSW Section 24 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PDC ENERGY INC /2N68W24
Location ID: 336426



Photo 1. Photo taken from the access road looking towards the location, facing East. The gravel has not been removed and compaction has not been alleviated along the access road.



Photo 2. Photo taken from the well location, facing North. A List B Colorado Noxious weed species, Canada thistle (*Cirsium arvense*), is found at the site.

Inspection Photos
Location Name: PDC ENERGY INC /2N68W24
Location ID: 336426



Photo 3. Photo taken from the well location, facing East.



Photo 4. Photo taken from the well location, facing West.
See comments from Photo 1.

Inspection Photos
Location Name: PDC ENERGY INC /2N68W24
Location ID: 336426



Photo 5 Photo taken from the well location, facing East. Electric left on site.



Photo 6. Photo taken from adjacent sod outside of the location, facing South. See comments from Photo 1.