

Inspection Photos  
Location Name: Lilli Unit #3-7  
Location ID: 331106



Photo 1: Wellhead



Photo 2: Location

**Inspection Photos**  
**Location Name: Lilli Unit #3-7**  
**Location ID: 331106**



**Photo 3: Stormwater erosion SW of location**



**Photo 4: Weeds in berms, low berms**

Inspection Photos  
Location Name: Lilli Unit #3-7  
Location ID: 331106




Photo 5: Unused equipment, debris, in shed



Photo 6: Unused separator