

Inspection Photos
Location Name: Lilli Unit #4-8
Location ID: 326763



Photo 1: Wellhead



Photo 2: Stained soil in engine house

Inspection Photos
Location Name: Lilli Unit #4-8
Location ID: 326763



Photo from prior inspection for comparison



Photo 3: Stained soil at wellhead.