

**Inspection Photos**  
**Location Name: Lilli Unit #12-4**  
**Location ID: 327147**



**Photo 1: Wellhead**



Inspection Photos  
Location Name: Lilli Unit #12-4  
Location ID: 327147



Photo from prior inspection for comparison



Photo 2: Weeds controlled outside of wellhead. Weeds around wellhead.

**Inspection Photos**  
**Location Name: Lilli Unit #12-4**  
**Location ID: 327147**



**Photo from prior inspection for comparison**



**Photo 3: Weeds along lease road controlled**