

Inspection Photos
Location Name: STANDLEY #6-2 5-2 8-3
Facility ID 275611/ 275610/ 275817



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos

Location Name: STANDLEY #6-2 5-2 8-3

Facility ID 275611/ 275610/ 275817



Photo 3. Stained soil around #6-2 wellhead



Photo 4. Unused unmarked riser