

**Inspection Photo
Federal KP 523-18
API # 045-19449
Inspection # 689301291**



Location Photo #1

Location Photo #2,

**Inspection Photo
Federal KP 523-18
API # 045-19449
Inspection # 689301291**



Location Photo #3, Weeds behind separators



Location Photo #4, Weeds next to heater treater

**Inspection Photo
Federal KP 523-18
API # 045-19449
Inspection # 689301291**



Location Photo #5, Stained rock in battery containment



Location Photo #6, Stained rock in battery containment

**Inspection Photo
Federal KP 523-18
API # 045-19449
Inspection # 689301291**



Location Photo #7, Stained rock in battery containment



Location Photo #8, Stained rock in battery containment

**Inspection Photo
Federal KP 523-18
API # 045-19449
Inspection # 689301291**



Location Photo #9, Faded Wellhead sign