

Inspection Photos
Location Name: MAHONEY #1
Facility ID 240322



Photo 1. Wellhead/ Stained soil



Photo 2. Tank battery

Inspection Photos
Location Name: MAHONEY #1
Facility ID 240322



Photo 3. Stained soil around wellhead and fanning out to the northwest.



Photo 4. Stained soil inside compressor house