

# *Inspection Photos*

*API#077-07361*

*Operator: Caerus*

*Inspection Number: 674104467*

*Inspection Date: 5/31/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Northwest.

May 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus PA Clyde Hall API#077-07361





### Photo#2:

Several areas of Location have less vegetation and are more compacted than surrounding soils; these areas appear to be where Facilities were located when looking at historical aerial imagery.

May 31, 2018





Photo#3:

Several areas of Location have less vegetation and are more compacted than surrounding soils; these areas appear to be where Facilities were located when looking at historical aerial imagery.

May 31, 2018



Photo#4: