

# *Inspection Photos*

*Loc#312406*

*Operator: Caerus*

*Inspection Number: 674104468*

*Inspection Date: 5/31/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from Entry to Northwest.

May 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Big Creek Loc#312406





Photo#2:

View over Interim Reclamation area to Southeast.

May 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Big Creek Loc#312406





**Photo#3:**  
It appears that Weeds have been controlled at this Location.



**Photo#4:**

May 31, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Big Creek Loc#312406