

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2018

Submitted Date:

06/08/2018

Document Number:

689701445**FIELD INSPECTION FORM**
 Loc ID 421108 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 5201 TRUXTUN AVENUE #100City: BAKERSFIELD State: CA Zip: 90339**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
White, Brent	970-285-2200	bwhite@bry.com	Production Foreman
Armstrong, Jon		jarmstrong@bry.com	
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent
Hogelin, Thomas		thogelin@bry.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293396	WELL	PR	07/29/2015	OW	045-14956	SCHOOL HOUSE POINT OM01B B21 696	PR
293397	WELL	PR	01/19/2016	OW	045-14957	SCHOOL HOUSE POINT OM01C B21 696	PR
421130	WELL	XX	01/29/2018	LO	045-20302	School House Point OM 07D B21 696	ND
421131	WELL	XX	01/29/2018	LO	045-20303	School House Point OM08B B21 696	ND
421132	WELL	PR	01/20/2016	OW	045-20304	SCHOOL HOUSE POINT OM08C B21 696	PR
421134	WELL	PR	01/20/2016	OW	045-20305	SCHOOL HOUSE POINT OM02D B21 696	PR
421135	WELL	PR	01/19/2016	OW	045-20306	SCHOOL HOUSE POINT OM08D B21 696	PR
421136	WELL	PR	01/20/2016	OW	045-20307	SCHOOL HOUSE POINT OM02B B21 696	PR
421138	WELL	XX	01/29/2018	LO	045-20308	SCHOOL HOUSE POINT OM07B B21 696	ND
421139	WELL	XX	01/29/2018	LO	045-20309	SCHOOL HOUSE POINT OM07A B21 696	ND
421140	WELL	XX	01/29/2018	LO	045-20310	SCHOOL HOUSE POINT OM07C B21 696	ND
421146	WELL	PR	09/12/2015	OW	045-20316	SCHOOL HOUSE POINT OM02C B21 696	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dry and dusty. Continue dust control.		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2200

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash and debris behind tank battery from construction work.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/19/2018

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pig Station	# 1		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containers at wells and separators.		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	100 BBLs	PBV STEEL		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	400 BBLs	HEATED STEEL AST		,
Comment:	3 of 6 400 bbl tanks not yet in service.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	293396	Type:	WELL	API Number:	045-14956	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293397	Type:	WELL	API Number:	045-14957	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421130	Type:	WELL	API Number:	045-20302	Status:	XX	Insp. Status:	ND
Facility ID:	421131	Type:	WELL	API Number:	045-20303	Status:	XX	Insp. Status:	ND
Facility ID:	421132	Type:	WELL	API Number:	045-20304	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421134	Type:	WELL	API Number:	045-20305	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421135	Type:	WELL	API Number:	045-20306	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421136	Type:	WELL	API Number:	045-20307	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	421138	Type:	WELL	API Number:	045-20308	Status:	XX	Insp. Status:	ND
Facility ID:	421139	Type:	WELL	API Number:	045-20309	Status:	XX	Insp. Status:	ND
Facility ID:	421140	Type:	WELL	API Number:	045-20310	Status:	XX	Insp. Status:	ND



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Culverts	Pass			
Gravel	Pass					
Ditches	Pass					
		Compaction	Pass			
				Material Handling And Spill Prevention	Pass	
Berms	Pass					
		Check Dams	Pass			
		Ditches	Pass			
Compaction	Pass					

Comment: [Continue dust control on roads.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401668865	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4489922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4489922</a>
689701446	Inspection 689701445 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4489918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4489918</a>