

# Final Reclamation and Stormwater Inspection

June 13, 2018

Operator: PAR PACIFIC HOLDINGS INC – 16800

Location ID: 409710

Inspection Document #: 674902212

Weld County, CO

NWNE Section 32 T3N R61W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: PAR PACIFIC HOLDINGS INC/3N61W32

Location ID: 409710



**Photo 1.** Photo taken from the access road looking towards the well location, facing Southwest. Appears the Operator has not performed any reclamation activities on the access road itself but has on the well pad location.



**Photo 2.** Photo taken from the well location, facing North. The reclamation operations have failed to generate perennial vegetation cover. Disturbance area is currently dominated by the annual List C Colorado Noxious Weed cheatgrass.

## Inspection Photos

Location Name: PAR PACIFIC HOLDINGS INC/3N61W32

Location ID: 409710



**Photo 3.** Photo taken from the facility, facing South. See comments from Photo 2.



**Photo 4.** Photo taken from the south end of the location, facing East. There is a fenced in pit area remaining on location that will need to be re-contoured and re-graded. See comments from Photo 2.

Inspection Photos

Location Name: PAR PACIFIC HOLDINGS INC/3N61W32

Location ID: 409710



**Photo 5.** Photo taken from the Northeast end of the location. There is an excavated barren area remaining on location that will need to be re-contoured and re-graded.



**Photo 6.** Close-up photo taken from the Northeast end of the location. See comments under Photo 5.