

Inspection Photo
Benzel 26-8B (H26NW)
API # 045-09505
Inspection # 6893013017



Location Photo #1



Location Photo #2, Stained Rock in battery containment