

**Inspection Photo
Benzel 25-10C (K25)
API # 045-09167
Inspection # 689301325**




Location Photo #1



**Location Photo #2, Stained rock in tank
containment**

Inspection Photo
Benzel 25-10C (K25)
API # 045-09167
Inspection # 689301325



Location Photo #3 Stained rock in tank containment



Location Photo #4, Stained rock in tank containment