

**Inspection Photo**  
**Benzel 36-2B (B36)**  
**API # 045-08045**  
**Inspection # 689301329**



**Location Photo #1**

**Location Photo #1**

**Inspection Photo  
Benzel 36-2B (B36)  
API # 045-08045  
Inspection # 689301329**



**Location Photo #3, Oily residue on outside of tank**



**Location Photo #4, Stained rock in tank containment**

**Inspection Photo  
Benzel 36-2B (B36)  
API # 045-08045  
Inspection # 689301329**



**Location Photo #5, Stained ground around wellhead**