

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2018

Submitted Date:

06/13/2018

Document Number:

689401372**FIELD INSPECTION FORM**Loc ID 334529 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**22 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Engineering		dnr_cogccengineering@state.co.us	All Engineering
Laramie Energy LLC		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278342	WELL	PR	02/01/2018	GW	077-08902	MCDANIEL 2-15	PR
278343	WELL	PR	01/01/2011	GW	077-08903	MCDANIEL 2-16	PR
278344	WELL	PR	08/01/2017	GW	077-08904	MCDANIEL 2-10	PR
278346	WELL	PR	09/21/2015	GW	077-08906	MCDANIEL 2-9	PR
292512	WELL	PR	03/01/2018	GW	077-09415	MCDANIEL 2-9A	PR
292513	WELL	PR	03/17/2009	GW	077-09414	MCDANIEL 2-10C	PR
292514	WELL	SI	01/01/2018	GW	077-09413	MCDANIEL 2-10B	PR
292515	WELL	PR	09/01/2013	GW	077-09412	MCDANIEL 2-10A	PR
292516	WELL	PR	09/10/2014	GW	077-09411	MCDANIEL 2-9C	PR
292517	WELL	PR	05/06/2014	GW	077-09410	MCDANIEL 2-9B	PR
292518	WELL	PR	03/17/2009	GW	077-09409	MCDANIEL 2-15C	PR
292519	WELL	PR	06/01/2017	GW	077-09408	MCDANIEL 2-15B	PR
292520	WELL	TA	09/12/2016	GW	077-09407	MCDANIEL 2-15A	TA
292521	WELL	PR	07/16/2009	GW	077-09406	MCDANIEL 2-16C	PR
292522	WELL	PR	03/17/2009	GW	077-09405	MCDANIEL 2-16B	PR
292523	WELL	PR	01/25/2016	GW	077-09404	MCDANIEL 2-16A	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Posted Emergency Contact Number 1-970-248-0497](#)

Corrective Action:

Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Wire panels		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	400 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	278342	Type:	WELL	API Number:	077-08902	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	278343	Type:	WELL	API Number:	077-08903	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	278344	Type:	WELL	API Number:	077-08904	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	278346	Type:	WELL	API Number:	077-08906	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	292512	Type:	WELL	API Number:	077-09415	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	292513	Type:	WELL	API Number:	077-09414	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			
Facility ID:	292514	Type:	WELL	API Number:	077-09413	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Well appeared to be producing at time of inspection.								
Corrective Action:						Date:			
Facility ID:	292515	Type:	WELL	API Number:	077-09412	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR w/ Plunger								
Corrective Action:						Date:			

Facility ID: 292516	Type: WELL	API Number: 077-09411	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 292517	Type: WELL	API Number: 077-09410	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 292518	Type: WELL	API Number: 077-09409	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 292519	Type: WELL	API Number: 077-09408	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 292520	Type: WELL	API Number: 077-09407	Status: TA	Insp. Status: TA
---------------------	------------	-----------------------	------------	------------------

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder:

Comment: Form 4 Doc#401400612 has been denied.

Corrective Action: Contact engineering group.

Date: 06/22/2018

Facility ID: 292521	Type: WELL	API Number: 077-09406	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 292522	Type: WELL	API Number: 077-09405	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR w/ Plunger

Corrective Action:

Date:

Facility ID: 292523	Type: WELL	API Number: 077-09404	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well			
Comment:	PR w/ Plunger		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Stormwater erosion appears to be controlled on the location at this time.						Date: _____
Corrective Action:						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401672158	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4493420
689401373	McDaniel 2-9 Pad Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4493411