



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the project area from the southwestern corner facing northward. Revegetation is progressing within outer reclamation areas with grasses such as Indian ricegrass (*Achnatherum hymenoides*), smooth brome (*Bromus inermis*), and western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the western portion of the project area from the northwestern corner facing southward.



Photo 4. View of erosional channel and tunneling in the southwestern project area, where concentrated stormwater flows down a diversion from the southern edge of the well pad. Photo is facing upstream toward the well pad.



Photo 5. View of erosional channel shown in photo 4, facing downstream. Channel is approximately 2.5 feet wide and deep. Stabilization measures are needed here.



Photo 6. View of Canada thistles (*Cirsium arvense*) within the northwestern interim reclamation area. Approximately 300 Canada and musk thistles observed.