



STATE OF
COLORADO

Allison - DNR, Rick <rick.allison@state.co.us>

Lucero 34-6 tank battery results

1 message

Allison - DNR, Rick <rick.allison@state.co.us>
To: TI ti <iverjt@msn.com>
Cc: "Axelson, John" <john.axelson@state.co.us>

Mon, Apr 30, 2018 at 11:09 AM

Mr. Iverson,

I have attached a copy of the laboratory analytical report for the soil samples collected by SRC Energy, Inc. at the Lucero 34-6 (and former Lucero 1-34) tank battery location. The laboratory analytical report shows that the soil at the Lucero 34-6 tank battery location is in compliance with the COGCC Table 910-1 Concentration Levels for organic and inorganic compounds in soil and no remediation is required at the location.

SRC Energy will be required to submit a final report with a site figure showing the locations of the soil samples that they collected from the tank battery. I will send you a copy of that report when I receive it. In the meantime, please let me know if you have any further questions.

Rick

Richard Allison, P.G.
Environmental Protection Specialist, Northeast Colorado



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

P 970.461.2970 | C 970.623.0850
1120 Lincoln Street, Suite 801, Denver, CO 80203
rick.allison@state.co.us | www.colorado.gov/cogcc



Y804385 Lucero 34-6 TB Vault Pit (Final).pdf
828K