

Inspection Photos
Well Name: Winter Flats 2-11-100
Location ID: 312519



Photo 1. Bird protection repaired.



Photo 2. Updated operator information

Inspection Photos
Well Name: Winter Flats 2-11-100
Location ID: 312519



Photo 3. Berm has not been repaired. Original corrective action and date still apply.



Photo 4. Stormwater issues have not been resolved. Original corrective action and date still apply.