

Inspection Photos
Location Name: Jones 1-11
API: 05-107-06093



Photo 1. Overview of location taken at entrance facing east.



Photo 2. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Jones 1-11
API: 05-107-06093



Photo 3. Stained soil at truck loadout.



Photo 4. Close-up of stained soil and trash bucket.

Inspection Photos
Location Name: Jones 1-11
API: 05-107-06093



Photo 5. Stained soil at truck loadout.



Photo 6. Close-up of stained soil.

Inspection Photos
Location Name: Jones 1-11
API: 05-107-06093



Photo 7. Stained soil at tank bases.



Photo 8. Close-up of stained soil.

Inspection Photos
Location Name: Jones 1-11
API: 05-107-06093



Photo 9. Stained soil at tank base.



Photo 10. Fresh gravel on location.