

Inspection Photos

API#081-07775

Operator: GRMR

Inspection Number: 674104487

Inspection Date: 7/7/2018





Photo#1:
Overview of Location to Northeast.; note predominance of Cheatgrass .

June 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Iles Mtn API#081-07775



Photo#2:

View to Southwest from middle of Location of Dalmatian toadflax & Cheatgrass.

June 7, 2018




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Iles Mtn API#081-07775



Photo#3:
Noxious Weeds, Dalmatian toadflax, Houndstongue & Thistle on what was Access road entry into Location.

June 7, 2018



Photo#4:



Photo#5:
View of Reference area Vegetation to North of Site .

June 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Iles Mtn API#081-07775