

Inspection Photos

Loc#312997

Operator: Santa Fe Natural Resources

Inspection Number: 674104489

Inspection Date: 6/18/2018





Photo#1:

Overview of Location to Southeast. Note B List Noxious weed , Scotch thistle plant in foreground.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res McIntyre Loc#312997



Photo#2:
Unused Equipment and Supplies stored on Location.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res McIntyre Loc#312997



Photo#3:

Ditch along Cut Bank side of Access road needs repair /additional BMPs.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res McIntyre Loc#312997



Photo#4:
Debris is scattered over Location.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res McIntyre Loc#312997



Photo#5:
Erosion transporting Sediment onto Location was noted in all Cut Slope areas.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res McIntyre Loc#312997



Photo#6:

Stained soil at Wellhead. Insert is of Rat hole partially covered with wooden slats in foreground of main photo indicated by arrow.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res McIntyre Loc#312997



Photo#7:

Buried fiberglass tank in tank battery. Insert is view through swing plate on top of tank indicated by arrow in main photo.

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res McIntyre Loc#312997



Photo#8:
Scotch thistle plants emerged & maturing on Location.



Photo#9:

June 18, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Santa Fe Natural Res McIntyre Loc#312997