

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/21/2018

Submitted Date:

06/21/2018

Document Number:

691400594**FIELD INSPECTION FORM**

Loc ID 321434	Inspector Name: Beardslee, Tom	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED															
2A Doc Num: _____			Findings: 2 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested															
Operator Information: OGCC Operator Number: <u>47120</u> Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u> Address: <u>P O BOX 173779</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>																		
Contact Information: <table border="1" style="width:100%"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Gomez, Jason</td> <td></td> <td>jason.gomez@state.co.us</td> <td></td> </tr> <tr> <td>,</td> <td></td> <td>COGCCinspections@anadarko.com</td> <td>All Inspections</td> </tr> </tbody> </table>				Contact Name	Phone	Email	Comment	Gomez, Jason		jason.gomez@state.co.us		,		COGCCinspections@anadarko.com	All Inspections			
Contact Name	Phone	Email		Comment														
Gomez, Jason		jason.gomez@state.co.us																
,		COGCCinspections@anadarko.com	All Inspections															
Inspected Facilities: <table border="1" style="width:100%"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>206941</td> <td>WELL</td> <td>SI</td> <td>05/01/2017</td> <td>OW</td> <td>013-06436</td> <td>VANTHUYNE 42-34</td> <td>PA</td> </tr> </tbody> </table>			Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	206941	WELL	SI	05/01/2017	OW	013-06436	VANTHUYNE 42-34	PA
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status											
206941	WELL	SI	05/01/2017	OW	013-06436	VANTHUYNE 42-34	PA											
General Comment: <div style="height: 300px; border: 1px solid black;"></div>																		

Inspected FacilitiesFacility ID: 206941 Type: WELL API Number: 013-06436 Status: SI Insp. Status: PA**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Well is plugged and abandoned, 1 riser remains on location.Corrective Action: Comply with Rule 603.f .Date: 07/21/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691400595	LOC PICS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4502058