

Inspection Photo
GGU Federal 23C-28-691
API # 045-19207
Inspection # 689301364



Location Photo #1



Location Photo #2

Inspection Photo
GGU Federal 23C-28-691
API # 045-19207
Inspection # 689301364



Location Photo #3, tank battery



Location Photo #4, Non Legible sign

Inspection Photo
GGU Federal 23C-28-691
API # 045-19207
Inspection # 689301364



Location Photo #5, Stained rock in between tanks



Location Photo #6, Stained rock in between tanks

Inspection Photo
GGU Federal 23C-28-691
API # 045-19207
Inspection # 689301364



Location Photo #7, Stained rock in between tanks



Location Photo #8, Stained rock in between tanks