

Inspection Photos

API#081-06682

Operator: Think Oil INC

Inspection Number: 674104497

Inspection Date: 6/7/2018





Photo#1:

View over what was Access road (darker green strip) to Location area to Southwest.

June 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Think Oil PA Silver ET AL API#081-06682



Photo#2:

View over Location to North east; arrow indicating Jeep parked on Farm track.

June 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Think Oil PA Silver ET AL API#081-06682



Photo#3:

Crop growth (density & height) in areas of Location are not commensurate with growth in surrounding field.

June 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Think Oil PA Silver ET AL API#081-06682



Photo4:
Canada thistle has emerged on what was Location Pad area.

June 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Think Oil PA Silver ET AL API#081-06682