

Inspection Photos  
Location Name: Shiras CTB S11  
Location ID: 451937



**Photo 1. Overview of location taken at entrance facing north.**



**Photo 2. Unlabeled container. Sand berm.**

Inspection Photos  
Location Name: Shiras CTB S11  
Location ID: 451937



Photo 3. Crude Oil NFPA diamond on tank labeled Produced Water.



Photo 4. No NFPA diamond on tanks.