

Inspection Photos  
Location Name: Grizzly 3-32H  
API: 05-057-06523



**Photo 1. Overview of location taken at entrance facing east.**



**Photo 2. Overflowing bucket at pump jack base.**